

Stan of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director

JOHN R. BAZA Division Director

Inspection Report Minerals Regulatory Program Report Date February 8, 2006



Mine Name: Eagle Canyon Operator Name: Georgia Pacific Permit number: M/015/050 **Inspection Date:** January 20, 2006

Time: 1:40-1:55 PM

Inspector(s): Paul Baker

Other Participants: Rebecca Doolittle (Price BLM) and two people with Georgia Pacific

Weather: Clear, 30's Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds		\boxtimes	
2. Public Safety (shafts, adits, trash, signs, highwalls)		닏	닏
3. Protection of Drainages / Erosion Control		닏	H
4. Deleterious Material			닏
5. Roads (maintenance, surfacing, dust control, safety)			님
6. Concurrent Reclamation			
7. Backfilling/Grading (trenches, pits, roads,			
highwalls, shafts, drill holes)			
8. Water Impoundments			님
9. Soils	닏	닏	님
10. Revegetation		닏	님
11. Air Quality		\sqcup	
12. Other	\boxtimes	\boxtimes	

Purpose of Inspection:

This site has been inactive for at least four years. When we saw a truck there, we decided to go and see what was happening.

Inspection Summary:

1. Permits, Revisions, Transfer, Bonds

The Division was recently notified of some organizational changes with Georgia Pacific. For this reason, the Division has prepared an addendum to the reclamation contract updating some of the ownership and control information in the reclamation contract.

12. Other

Two people were at the site. One of them was in a dozer pushing material up from one of the pits (Photos 1 and 3). We assume this material is being loaded and hauled to the plant in Sigurd where, we were told, the plant is being reactivated. The mine is active about two days a week.

Inspection Date: January 20, 2006; Report Date: February 8, 2006

Page 2 of 2 M/015/050

Conclusions and Recommendations:

There is soil in an area to the east of the active pit (see the right side of Photo 3), and if this pit is expanded in this direction, the operator needs to salvage this soil.

1 RM Date: 3/13/06

PBB:pb

cc:

Operator

Rebecca Doolittle, Price BLM

Attachment: Photos

 $P:\GROUPS\MINERALS\WP\M015-Emery\M0150050-EagleCanyonQuarry\Final\ns-01202006-eagle.doc$

ATTACHMENT

Photographs

M/015/050, Eagle Canyon Quarry, Georgia Pacific Inspection Dated: January 20, 2006; Report Dated: February 8, 2006



Photo 1. The operator was pushing material up from one of the pits. A loader can be seen in the background.



Photo 2. A small dozer in another pit.



Photo 3. Another view of the pit in Photo 1. Note th soil on the right side of this picture.